





Ø	Preț (цена), lei		
	PN 12,5	PN 10	PN 4
presiunea (давление)	PN 12,5 – cu inel de arm (с арм. кольцом)		
PN 10 – fără inel de arm (без арм. кольца)	без болтов		
Branșament, 2 șurubi (тройник-хомут, 2 болта) 	20×½		
	25×½		
	25×¾		
	32×½		
	32×¾		
	32×1"		
	40×½		
	40×¾		
	40×1"		
	40×1" PVC		
	50×½		
	50×¾		
50×1"			
50×1"¼			
Branșament, 4 șurubi (тройник-хомут, 4 болта) 	63×½		
	63×¾		
	63×1"		
	63×1"¼		
	63×1"½		
	75×½		
	75×¾		
	75×1"		
	75×1"¼		
	75×1½		
	75×2"		
	90×½		
	90×¾		
	90×1"		
	90×1"¼		
	90×1"½		
	90×2"		
	110×½		
	110×¾		
	110×1"		
	110×1"¼		
	110×1"½		
	110×2"		
	110×2"½		
	110×3"		
	125×1"		
	125×1"¼		
	125×2"		
	140×1"		
	140×1"¼		
	140×2"		
	140×3"		
160×1"			
160×2"			
160×3"			
160×4"			
200×1"			
200×2"			
200×3"			
200×4"			
225×1"			
225×1"¼			
225×2"			
250×2"			
250×3"			
250×4"			
315×4"			

Ø	Preț (цена), lei		
	PN 12,5	PN 10	PN 4
presiunea (давление)	PN 12,5 – cu inel de arm (с арм. кольцом)		
PN 10 – fără inel de arm (без арм. кольца)	без болтов		
Branșament dubl. 4 șurubi (крест- хомут, 4 болта) 	50×¾		
	63×¾		
	75×¾		
Branșament p/u țeava metal. (тройник- хомут для метал. трубы) 	100×1"		
	120×1"		